


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1/97 To (mo./yr.) 12/97
2. DOGM File Number (Mine No): 910031017
3. Mine Name: GREEN BEETLE
4. Mineral(s) Mined (or permitted to mine): MICACEOUS QUARTZITE SCHIST
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
____ 1/4, SE 1/4, SE 1/4, Section 36, Township 11N, Range 16W
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
____ 1/4, ____ 1/4, ____ 1/4, Section _____, Township _____, Range _____
7. Name of Operator or Company: WILLIAM L BOWN
8. Permanent Street Address: 842 WEST 400 NORTH
City, State, Zip: WEST BOUNTIFUL, UTAH 84087
Phone: 801-295-0601
9. Company Representative (or designated operator):
Name: WILLIAM L BOWN
Title: OWNER
Business Address: 842 WEST 400 NORTH
City, State, Zip: WEST BOUNTIFUL, UTAH 84087
Phone: 801-295-0601
☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 172 TONS
3. If inactive, what year was the mine last active? _____

3. How much **additional acreage** was disturbed during the past year? APPROX. .20 ACRE
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
AN ACCESS ROAD WAS BLADED INTO THE "LOWER PIT" AREA
ALSO. A STORAGE AREA WAS CLEARED BETWEEN THE UPPER
AND LOWER PITS
5. How much acreage was **reclaimed** during the past year? APPROX. 1.5 ACRE
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
THE EXISTING PROCESS AREA WAS BLADED AND RIPPED. THE OLD
WASTE ROCK WAS PUSHED BACK INTO THE ~~NEW~~ "UPPER PIT"
TRENCH. NO SEEDING WAS DONE, BUT WILL BE COMPLETED IN
SPRING '98.
7. What is the **total disturbed acreage** at years end? 3.0 (APPROX.)
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
COMPLETE TOTAL RECLAMATION OF "UPPER PIT" DISTURBANCE
CONTINUE WORKING "LOWER PIT" AREA FOR BULK MATERIAL
REMOVAL. ALSO RESEED "STORAGE AREA" IF IT IS DETER-
MINED THAT WE NOT USE IT THIS YEAR.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): WILLIAM L BOWN

Title of Operator: OWNER

Signature of Operator: William L Bown

Date: 1-29-98